

Glass Processing Technology
Mr. Ramesh Kumar Chouhan
Department of Civil Engineering
Indian Institute of Technology, Madras

Lecture - 65

Internal Process Loss – Part II

(Refer Slide Time: 00:21)



Tempering



- Roller wave
- Furnace Breakage
- Chiller Breakage
- Unstable in furnace
- Coating Burn
- Spots
- Appearance
- Internal Crack
- Bend / Bow
- Spontaneous Breakage
- Coloured zones / anisotropy / iridescence / leopard spots /strain pattern

The slide features a blue header with the title 'Tempering' and a 'GLASS ACADEMY' logo. The content is a bulleted list of defects. At the bottom, there is a decorative blue bar with white icons representing various glass processing equipment and tools.

Now, we will discuss on tempering department, what are the issues occurs in tempering? Because of these issues glass gets rejected, roller wave, furnace breakage, chiller breakage, unstable in furnace, coating burn, spots, appearance, internal crack, bend and bow, spontaneous breakage, coloured zones, leopard spots, strain pattern etcetera. These are the major defects if machine is not set properly or parameters are not set properly in tempering machine.


(Refer Slide Time: 01:07)

Tempering

Machine error



1. Machine behaviour
2. Operating skill





Now, let us discuss tempering, now, in tempering also we have to define whether it is a machine error or operating skill is missing, we need to check all the parameters like roller wave.

(Refer Slide Time: 01:20)

Defects & Corrective measures


 

Defects	Figure	Reason	Corrective Measurements
Roller Wave		<1> Temperature High <2> Roller Arrangement Improper	<1> Reduce Temperature / Heating Time <2> Align Rollers Properly



What could be the reason for having roller wave on glass? Temperature is high or roller arrangement is improper, what is the corrective action to be taken need to reduce temperature heating time. And second is align rollers properly, this corrective action will reduce your roller wave. Then we observe furnace breakages.

(Refer Slide Time: 02:09)



Defects	Figure	Reason	Corrective Measurements
Furnace Breakage		<ol style="list-style-type: none">1. Glass Has Cracks2. Thermal Shock Is Large3. Furnace Temperature Is High While Loading Thick Glass4. Glass Is Already Tempered Or Heat Strengthened	<ol style="list-style-type: none">1. Manufacture Float Glass Without Cracks2. Avoid Loading Glass At Very Low Temperatures3. Reduce Temperature To Less Than 680 To 690°C From 720°C (Thin Glass)4. Never Load Furnace With Already Treated Glass


Breakages happens in glass, the reasons are glass must be having some crack or thermal shock is large, may be furnace temperature is high while loading thick glass and may be glass is already tempered or heat strengthened. These are the reasons because of which furnace breakage happens. And now let us understand what are the corrective actions?

Need to check glass and avoid if there is any crack in the glass. Avoid loading glass at very low temperature, reduce temperature to less than 680 to 690 centigrade from 720 for thin glass. Never load furnace with already never load furnace with glass which is already been tempered. This will avoid this will avoid furnace breakages and you will have good quality of glass.

(Refer Slide Time: 03:44)

Defects & Corrective measures



Defects	Figure	Reason	Corrective Measurements
Breakage In Chiller		<ol style="list-style-type: none"> 1. Glass Is Unable To Withstand Cooling 2. Edge Of Glass Is Not Proper (Has Nicks And Hairline Cracks) 3. Heating Time Is Too Short Or Uneven 4. Glass Has Increased Surface Area Due To Sharp Notches And Cut Holes 5. Quench Pressure Is Too High (Especially For Thick Glass) 6. Some Nozzles Are Clogged, Problem Of Flatness Exists 	<ol style="list-style-type: none"> 1. Increase Heating Time Or Furnace Temperature 2. Make Sure Glass Has Proper Edges 3. Check For Furnace Type - If Only Radiation, Change To Convective Heating (This Avoids Uneven Heating) 4. Increase Heating Time 5. Change Nozzle Opening 6. Check For Blocked Nozzles


Another area of concern is breakages in chiller, reasons are glass is unable to withstand cooling, edge of glass is not proper there is a hair line crack in the glass. Heating time is too short or uneven glass has increased surface area due to sharp notches and cut holes. Quench pressure is too high specially for thick glass, some nozzles are clogged problem of flatness exists.

Corrective measures are increase in heating time of furnace temperature. Make sure glass has proper edge polish, check for furnace type if only radiation change to convective heating. This will avoid uneven heating. Increase heating time, change nozzles or clean nozzles, because nozzles should have a proper opening, check your nozzles of course.

(Refer Slide Time: 04:39)

Defects & Corrective measures







Defects	Figure	Reason	Corrective Measurements
Unstable In Furnace		1. Glass Temperature In Middle Is Lower Than On Edges	<ol style="list-style-type: none"> 1. Increase Temperature In The Middle By Changing Temperature Profile 2. Adjust Convection In Furnace By Changing Heating Balance 3. Increase Heating Time

Unstable in furnace, glass temperature is lower than on edge that is middle of the glass temperature is high and at the end at the edges repeat. Unstable in furnace; glass temperature in middle is lower than on edges, this could cause problem. Corrective action is increase temperature in the middle by changing temperature profile, adjust convection in furnace by changing heating balance, increase heating time. So, you will be able to avoid instability in furnace.

(Refer Slide Time: 05:29)

Defects & Corrective measures






Defects	Figure	Reason	Corrective Measurements
Coating Burn On Surfaces		1. Coating Unable To Withstand Heat	1. Reduce Heating Time And Top Temperature


Coating burning on surface; reason is coating is unable to withstand the heat and corrective measure is reduce heating time and top temperature.

(Refer Slide Time: 05:46)

Defects & Corrective measures




Defects	Figure	Reason	Corrective Measurements
Coating Burn On Edge		<ol style="list-style-type: none"> 1. Kerosene Was Used As Cutting Oil 2. Finger Marks Of Operator Present In Glass 	<ol style="list-style-type: none"> 1. Avoid Using Kerosene As Cutting Oil. Use Oil Recommended By Cnc Cutting Machine Manufacturers 2. Never Allow Glass To Have Finger Marks Inside (It Contains Body Oils Whose Fire Point Is Less Than 620°C)





Coating burn on edge may be kerosene or cutting oil is used excessive, there are finger marks on glass because operator has not handled properly. And the corrective measure is avoid using kerosene and cutting oil and only use oil recommended by CNC cutting machine manufacturer. Never allow glass to have finger marks inside, because it will again lead to a coating burn, spots, coating scratches, reasons are glass is too hot when it comes out of furnace.

(Refer Slide Time: 06:30)

Defects & Corrective measures




Defects	Figure	Reason	Corrective Measurements
Spots / Coating Scratches		<ol style="list-style-type: none"> 1. Glass Is Too Hot When It Comes Out Of Furnace 2. Lumps Have Accumulated In Roller Surface 3. Coated Side Was Placed Upside Down 4. Glass Temp Is Less 	<ol style="list-style-type: none"> 1. Reduce Temperature Of Furnace Or Heating Time 2. Clean The Ceramic Rollers 3. Never Place Coated Side On Rollers 4. Increase The Heating Time Or Increase The Quenching Pressure





Lumps have accumulated in roller surface coated side was placed upside down glass temperature is low. Corrective measures are reduce temperature of furnace or heating time, clean the ceramic rollers never place coated side on rollers I mean glass, increase the heating time or increase the quenching pressure.

(Refer Slide Time: 06:51)

Defects & Corrective measures





Defects	Figure	Reason	Corrective Measurements
Appearance		<ol style="list-style-type: none"> 1. So₂ Gases Were Used Insufficiently 	<ol style="list-style-type: none"> 1. Temporarily Increase So₂ Gas Flow




Appearance, reason is So₂ gases were used inadequately corrective measure is temporarily increases So₂ gas flow and appearance will come in live.

(Refer Slide Time: 07:06)

Defects & Corrective measures







Defects	Figure	Reason	Corrective Measurements
Internal Crack		1. Glass Was Too Cold When It Left Furnace For Chiller	1. Increase Temperature

Internal crack, reasons are simple glass was too cold when it left furnace for chiller and corrective measure is increase your temperature.

(Refer Slide Time: 07:18)

Defects & Corrective measures



Defects	Figure	Reason	Corrective Measurements
Bend		1. Top Surface Temperature Of Glass Is Higher Than Bottom Surface Temperature When Glass Comes Out Of Furnace 2. Top Side Quenching Power In Chiller Is Lower Than Bottom Side Top Surface Temperature Of Glass Is 3. Lower Than Bottom Temperature When Glass Comes Out Of Furnace 4. Top Side Quenching Power In Chiller Is Higher Than Bottom Side	1. Increase Bottom Temperature Of Furnace Or Decrease Heating Balance Pressure 2. Set Furnace Temperature Properly So That Chiller Air Pressure Is Adjusted 3. Reduce Furnace Bottom Temperature Or Increase Heating Balance Pressure 4. Increase Chiller Bottom Quenching Power


Bend observing glass, the reasons are very simple top surface temperature of glass is higher than bottom surface temperature when glass came out of furnace. Top side quenching power is chiller is lower than bottom side. Corrective measures are increase bottom temperature of furnace or decrease heating balance pressure. Set furnace temperature properly, so that chiller air pressure is adjusted. Reduce furnace bottom

temperature or increase heating balance pressure, increase chiller bottom quenching power. These corrective measures will make sure that bends are bend in glass is avoided.

(Refer Slide Time: 08:05)

Defects & Corrective measures







Defects	Figure	Reason	Corrective Measurements
Spontaneous Breakage		1. Presence Of Nis / Raw Glass Impurities	1. Heat Soak Test Req. For Toughened Glass

Spontaneous breakage, reason is very simple presence of Nis in raw material. Corrective measure is heat soak test can be done, so that spontaneous breakage is avoided.

(Refer Slide Time: 08:22)

Defects & Corrective measures

Defects	Figure	Reason	Corrective Measurements
Coloured Zones / Anisotropy / Iridescence / Leopard Spots / Strain Pattern		Uneven Heating / Cooling	<ol style="list-style-type: none"> 1. Heating: Decrease Your Furnace Temperature And Increase Your Heating Time 2. Heating: Set The Longest Possible Oscillation Length 3. Quenching: Clean Your Quench Nozzles. 4. Quenching: Optimize The First Stopping Point. 5. Good Care Of Machines

Now, coloured zone leopard spots or strain pattern, reason is simple uneven heating or cooling, decrease your furnace temperature and increase your heating time. Set the

longest possible oscillation length, clean your quench nozzles, optimize the first stopping point and of course good care of machine.

(Refer Slide Time: 08:48)

Summary:

By the end of this video, you have learnt about the:

- Internal process loss in Tempering
- Defects and corrective measures of Roller wave, Furnace breakage, Chiller breakage, Unstable furnace, Coating burn on surfaces, Coating burn on edge, Spots/coating scratches, Appearance, Internal crack, Bend, Spontaneous breakage, Pattern/colored zones

